




The following 9 photographs show April 2006 conditions in Mark West Creek over the course of ½ mile of creek





Landslide repair 245 Wappo Road November 2007







January 2006 -Landslide material discharging into north fork Mark West Creek. Mr. Casey Caplinger in photograph



January 2006 - Landslide material North Fork Mark West Creek